Pittsburgh May 13th 1854

Professor Booth

Sir

As per request of the Treasury Department I this day send you by Adams Express three Safety Guards In two of the Guards I have sent. You ~~you~~ will observe that there is a small hole in the bottom of the Spindles in filling the Guards with alloys these holes must be first filled and then set over the pivot on which they move and then poore in the alloy otherwise these holes will contain air which expands and prevents the cups from being filled

Very Respectfully

C Evans

1854
May 18th
C Evans
Pittsburg
Pa.